# Scope of Work – DPM Benbrook Texas

## Base Flashings – Parapet Wall, Curb and Expansion Joints

- 1. Perform alternating 3-course application of mastic and reinforcement fabric to all breaks, holes, splits or suspect weak points in the existing BUR flashings.
- 2. Install new aluminum or white roof coating to all Base Flashings after performing above mentioned maintenance repairs.

## Parapet Walls – Above Base flashings

- 1. Remove existing coping metal and fully adhere new TPO Membrane to the parapet wall extending the membrane up and over the wall.
- 2. Install new 2-piece fascia metal to the top of the wall. Fascia metal Contractor's choice of 24G Kynar Coated Metal or .040 Kynar Coated Aluminum.

## **Deck Replacement**

 Include in the cost for this project the removal of 20 ft. x 20 ft. of BUR Roofing and existing metal decking. Install new metal decking, insulation and 2-ply torch applied modified Bitumen roofing system to this repair area. Spud gravel to bare surface felts a minimum of 2 feet onto surrounding built up roof. Feather new roof system 18 inches onto primed prepared roof surface. Finish tie in with 3-course alternating application of mastic and reinforcement fabric between the 2-ply roof and the existing BUR.

#### **New Curb Flashing**

1. Figure in the cost of this project the installation of new 2 ply BUR flashings to Four (4) 4 ooft by 8 Foot curbs to be installed by others during the course of the project.

#### **Contingency Allowance**

1. Include in your cost for the project \$10,000 in contingency dollars to be used for unforeseen items or at the Owner's discretion.

#### **Future Leak Calls**

1. Include in cost three (3) return leak calls for 1 year following the completion of the project.

## End of Scope of Work